


ELEVATION





ROOF



Architectural Shingle Roof


Non Hip Roof Configuration

ROOF DECK ATTACHMENT



Minimum ½ inch plywood, 6 inch nail pattern, 8d nails, SWR present

ROOF TO WALL ATTACHMENT



Toenail, metal connectors does not meet requirements of clip. Only 1 nail present.

OPENING PROTECTION

N/A

INSPECTOR'S CERTIFICATION



INSPECTORS COMMENTS

Architectural Shingle Roof was in serviceable condition.

No glazing protection was present.